

101-7/7/1995-00438

(804) 322-4776

5090
1822:JFH:cag

07 JUL 1995

Certified Mail-Return Receipt Requested

U.S. Environmental Protection Agency

Attn: Mr. David Toth

Mail Code: 3HW61

Region III

841 Chestnut Building

Philadelphia, Pennsylvania 19107

Re: Results of Additional Fieldwork at SWMU 11-
Firefighting Training Area, NAS Oceana

Dear Mr. Toth:

After our phone conversation on March 17, 1995, and from previous conversations with Mr. Joel Hennessy and Ms. Betty Ann Quinn of your support branch, two additional monitoring wells were installed and sampled at SWMU 11 at NAS Oceana. A figure accompanying the March 28, 1995 letter illustrated the approximate well locations. The wells were sampled for 8240 VOCs, PAHs, TPH and TAL metals (filtered and unfiltered). The analytical test for metals was SW-6010/7000.

The attached technical memorandum presents the sampling locations, analytical results from the two additional wells, and summarizes the complete groundwater characterization study for SWMU 11 through the complete RFI/CMS program. As stated in the memorandum, no further action is necessary based on the analytical results, and it is recommended that SWMU 11 be removed from the RCRA corrective action program.

Please call Mr. Jim Harris, RPM, at (804) 322-4776 if you have questions or need additional information with regards to this submittal.

Sincerely,

J. F. HARRIS, P.E.
Remedial Project Manager
Installation Restoration Section
(North)
Environmental Programs Branch
Environmental Quality Division
By direction of the Commander

Re: Results of Additional Fieldwork at SWMU 11-
Firefighting Training Area, NAS Oceana

Enclosure

Copy to:
USEPA (Mr. Harry Daw, Chief, 3HW61)
NAS Oceana (Mr. Will Bullard)
VDEQ (Ms. Erica Dameron)

Blind copy to:
1822 (JFH)
18S
epalladd.jfh